

EXPERIENCE FRANK RADEMAKER



2019 – 2015

Reactivation superintendent of a cold stack laid up offshore support vessel UK, 2019

After 2 years of cold stack laid up the vessel was purchased “as is where is” by the principal. The vessel went to dry dock in the UK as a dead tow. Underwent repairs, maintenance, testing and certification by Flag and Class.

At the same time the vessel was outfitted with a moon pool and a geotechnical drill spread.

Vessel superintendent of several geophysical survey vessels

The Netherlands, Singapore & Egypt, 2017-2015

Also assisted principal with pre-management, change of flag & condition survey's (including CAP) for newly acquired vessels and “ship of opportunity”.

Superintendent for mobilization of cable laying, rock-cutting & water-jetting barge

Singapore, 2018

Outfitting of a chartered barge with rented project equipment, power plant and welfare units with a project team at the site supported by a project team at the principal's office. Yard logistics and crange also dealt with by site team.

2014 – 2011

Site managing of construction of a FCS 3307

Malawi, 2014-2013

The Malawi Lake Services was privatized and recently managed by a Portuguese multidisciplinary construction company. The company had also taken over the Monkey Bay shipyard at lake Malawi.

As to insure a reliable link between the mainland and the island Likoma and surrounding islands a new fast ferry was acquired, which could also be considered a political gesture to the occupancies of the islands.

Damen Shipyards delivered a building package, tools and skilled labour to construct a FSC 3307 locally.

Taking over of two vessels by principal

Singapore, Malaysia, 2012

Pre management and tendering of repair yards;
Change of flag to Bahamas;
Study change of flag to Indonesia.

Certification, upgrade and mobilization of mv “Mwongozo”

Tanzania, 2012-2011

Principal was rewarded a tender for seismic survey works in lake Tanganyika. Mv “Mwongozo” owned by the Tanzanian government was hired as a platform for the mentioned survey works.

Inspection of vessel and local facilities at great lakes;
Selection of equipment and labour locally and from Europe;
Review stability and incline test by European naval architect;

Cost and time control;
Organize and supervise of dry dock and in water repairs & upgrade at the lake Tanganyika;
Certification of the vessel in accordance with Tanzanian & IMO regulations.



2013 – 2005

Hull and machinery survey

Fifteen casualties related Hull & Machinery surveys in the port

Antwerp, Flushing and Rotterdam

Casualties like:

Over pressurized tank of chemical tanker;
Collision damage between reefers;
Propeller damage due to grounding of RoRo vessel;
Heavy weather damage on deck of a reefer;
Damage of propulsion gear of chemical tanker.

Yard commissioning

Pre commissioning coordination of top site of light drill ship

Norway, 2009

Commissioning of two Damen ferries

China, 2008

Commissioning of cargo vessel

Ukraine, 2007

Commissioning of several Damen tugboats

Romania, 2006



OTHERS

Prepare Condition Assessment Program (CAP) for a small offshore support vessel Seychelles 2019

Application of vessel registration at Malaysian flag 2017

Mobilizing of a BOP for a light drill ship Scotland, 2013

Scouting for vessels and facilities at lake Tanganyika and lake Malawi Tanzania & Malawi 2012 & 2013

Registration of survey vessel at Bahama Maritime Authorities 2011

Survey, cost calculation and commercial proposal of dredger and tug boats Libya & The Netherlands

Superintendent during dry dock of survey vessel Singapore, 2008

Approval surveys of several tugboats Italy, 2008

Superintendent during dry dock of cargo vessel Portugal, 2007

Client representative during dry dock of a survey vessel United Arab Emirates, 2005